

# Federal Energy Act Report

October 1, 2008 thru September 30, 2009

(Public Record Posted Date: December 1, 2009)

## General Information:

Total Number of Active UST Facilities: **8,040**  
 Total Number of Active/Inactive USTs: **21,898**

## Summary Information For On-Site Inspections:

Number of UST Facilities Inspected: **3,048**  
 Percent of UST Facilities in SOC Compliance: **60**

## Summary Information For Releases:

Number of Confirmed UST Releases: **326**

## Sources and Causes of Environmental Releases from Underground Storage Tanks in Illinois

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	291	89.3	3	0.9	4	1.2	67	20.6	47	14.4	2	0.6	24	7.4	144	44.2
Piping	4	15.6	2	0.6	1	0.3	1	0.3	0	0	0	0	0	0	0	0
Dispenser	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Submersible (STP)	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Delivery Problem	97	29.8	43	13.2	54	16.6	0	0	0	0	0	0	0	0	0	0
Other	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
<b>Totals</b>	<b>392</b>	<b>134.7</b>	<b>48</b>	<b>14.7</b>	<b>59</b>	<b>18.1</b>	<b>68</b>	<b>20.9</b>	<b>47</b>	<b>14.4</b>	<b>2</b>	<b>0.6</b>	<b>24</b>	<b>7.4</b>	<b>144</b>	<b>44.2</b>

(source of data: Illinois Environmental Protection Agency)

**Note:** Since a release could be from more than one source and/or could have more than one cause, the percentages within source and cause do not add up 100. For the same reason, the release numbers for each category within source and cause do not add up to total number of confirmed releases.